Product data sheet

# XUY318NC2N02S32

Photoelectric roller sensor XUY, 318 mm, NC

## Main

| | |
|---|---|
| ETIM classification | ETIM 9 - EC002651 - Optical fibre sensor/optical fibre amplifier |
| Indivisible sale quantity | 1 |

## Offer Sustainability

| | |
|---|---|
| California proposition 65 | WARNING: This product can expose you to chemicals including: Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. Fo more information go to www.P65Warnings.ca.gov |

## Warranty

| | |
|---|---|
| Warranty | 18 months |

## Packing Units

| | |
|---|---|
| Country of origin | FR (France) |
| Unit type of package 1 | PCE |
| Number of units in package 1 | 1 |
| New Package 1 GTIN-13 | 3666916001615 |
| Package 1 height | 9 cm |
| Package 1 width | 9 cm |
| Package 1 length | 63 cm |
| Package 1 weight | 0.8 kg |
| New Package 2 GTIN 14 | 13666916001612 |
| Package 2 height | 9 cm |
| Package 2 width | 9 cm |
| Package 2 length | 63 cm |
| Package 2 weight | 0.8 kg |
| New Package 3 GTIN 14 | 23666916001619 |

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein.
This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications.
It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof.
Neither TMSS Holding nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein.